

Notes:

- Precast Manhole Shall Conform To ASTM C-478-78a As Manufactured By: York Concrete Septic Tanks Inc. York Pa. Or An Approved Equal.
- Bench And Channel Shall Be Brick Or Hand Formed Concrete. Min. Thickness Of 4", Bench Shall Slope To Top Of Pipe 1/2" Fall Per Foot.
- 3. Mortar Shall Be "Type S".
- 4. Manhole Steps Required Over The Effluent Side As Shown.

| APPROVAL | REVISED | TOWN OF EASTON |
|---|-----------|----------------------|
| Tallot Whome 4/25/06 EU MANAGER OF ENGINEERING DATE | MAY 1, 89 | |
| | AUG 1, 94 | EASTON UTILITIES |
| | MAR 1, 98 | STANDARD DETAILS |
| | FEB 1, 02 | PRECAST CONCRETE |
| | | MANHOLE |
| ISSUED: <u>MAY 1, 1986</u> | | STANDARD NO. SD-4.00 |